



REPUBLIC OF THE PHILIPPINES
DEPARTMENT OF BUDGET AND MANAGEMENT
GENERAL SOLANO STREET, SAN MIGUEL, MANILA

SUPPLEMENTAL/BID BULLETIN (SBB) NO. 1

This SBB No. 1 dated November 19, 2024, for **Project ID No. DBM-2025-05-EPA, “CISCO Equipment Licenses and Support Services Subscription,”** is issued pursuant to Section 22.5 of the 2016 Revised Implementing Rules and Regulations of Republic Act No. 9184, to clarify, modify or amend items in the Bidding Documents. Accordingly, this shall form an integral part of the Bidding Documents.

PARTICULAR(S)/QUERY(IES)	AMENDMENT(S)/CLARIFICATION(S)
<p>Queries:</p> <ol style="list-style-type: none"> 1. SLCC Eligibility: We are respectfully appealing about the SLCC if the agency would consider and allow projects that are procurement in nature of network equipment as reference for this project. We fully believe that either the project is a procurement of network equipment or renewal, both cover the same objective of providing a license and support maintenance. 2. Support Services: From the serial numbers listed below, we would like to request if we can get a “show tech” output command. The objective is for Cisco to assess eligibility for support services as part of the Services Compliance Support program. <ul style="list-style-type: none"> • FCH1932V3EN • FGL2409LHE0 • FGL2409LH9T 	<p>Clarifications:</p> <ol style="list-style-type: none"> 1. No, this is not considered. The completed contract must specifically focus on providing software licenses, technical support, and maintenance services for CISCO products ONLY. This includes access to software updates, technical assistance, and hardware replacement services. 2. Please see attached “Annex A” providing you the “show tech” output command for the serial numbers listed below: <ul style="list-style-type: none"> • FCH1932V3EN • FGL2409LHE0 • FGL2409LH9T

Other matters:

- The “No Contact Rule” shall be strictly observed. Bidders are not allowed to communicate with any member of the Bids and Awards Committee, Technical Working Group or Secretariat effective November 26, 2024, right after the opening of bids.
- For guidance and information of all concerned.



RAMON VICENTE B. ASUNCION
Assistant Secretary
Vice Chairperson, DBM-BAC

Annex A

```
FCH1932V3EN.txt Download Save to OneDrive
(Cisco Controller) >show tech-support

-----show boot-----
Primary Boot Image..... 8.10.171.0 (default) (active)
Backup Boot Image..... 8.10.151.0
-----show time-----
Time..... Mon Nov 18 17:52:05 2024
Timezone delta..... 0:0
Timezone location.....
-----show inventory-----
System Inventory
Burned-in MAC Address.....
Power Supply 1..... Present, OK
Power Supply 2..... Present, OK
Maximum number of APs supported..... 1500
-----show udi-----
NAME: "Chassis" , DESCR: "Cisco 5520 Wireless Controller"
PID: AIR-CT5520-K9, VID: V01, SN: FCH1932V3EN
-----show sysinfo-----
System Information
Manufacturer's Name..... Cisco Systems Inc.
Product Name..... Cisco Controller
Product Version..... 8.10.171.0
RTOS Version..... 8.10.171.0
Bootloader Version..... 8.3.15.177
Emergency Image Version..... 8.2.166.0
```

```
FGL2409LHE0.txt Download Save to OneDrive
*****
***** PuTTY log 2024.11.18 18:33:54 *****
sho tec
DBM-ARCADE-WLAN-AP-2F-L3#sho tech-support
***** show version *****
Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to
restrictions as set forth in subparagraph (c) of the Commercial
Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and
subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer
Software clause at DFARS sec. 252.227-7013.

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, California 95134-1706

This product contains cryptographic features and is subject to United
States and local country laws governing import, export, transfer and
use. Delivery of Cisco cryptographic products does not imply
third-party authority to import, export, distribute or use encryption.
Importers, exporters, distributors and users are responsible for
compliance with U.S. and local country laws. By using this product you
agree to comply with applicable laws and regulations. If you are unable
to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
http://www.cisco.com/wll/export/crypto/tool/stgrg.html

If you require further assistance please contact us by sending email to
annet@cisco.com
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2024 by Cisco Systems, Inc.
Compiled Fri May 10 05:09:16 GMT 2024

ROM: Bootstrap program is U-Boot boot loader
BOOTLDR: U-Boot boot loader Version 2013.01-gacaad15 (Aug 18 2019 - 20:12:19)

DBM-ARCADE-WLAN-AP-2F-L3 uptime is 0 days, 0 hours, 7 minutes
Last reload time : Thu Nov 7 10:03:34 UTC 2024
Last reload reason : unknown

Cisco AIR-AP2802I-A-K9 ARMv7 Processor rev 1 (v7l) with 1028192/580468K bytes of memory.
Processor board ID FGL2409LHE0
AP Running Image : 8.10.196.0
Primary Boot Image : 8.10.196.0
Backup Boot Image : 8.10.130.0
Primary Boot Image Hash: 5211acb530cc96d3d7f13a29a968856ea0d806d9ea87771a6b1f36ab765ba481ead3eba2f9ab8a428574
Backup Boot Image Hash:
2 Gigabit Ethernet interfaces
2 802.11 Radios
Radio Driver version : 9.0.5.5-W8964
Radio FW version : 9.1.8.1
NSS FW version : 2.4.30

Base ethernet MAC Address :
Part Number : 0-000000-00
```

```
AP3C51.0E3E.4594#
AP3C51.0E3E.4594#show ter
AP3C51.0E3E.4594#terminal le
AP3C51.0E3E.4594#terminal length 0
AP3C51.0E3E.4594#sh te[03/01/2020 00:01:58.7700] wired0 emac 2: link up
[03/01/2020 00:01:58.8300] wired0: link up
c
AP3C51.0E3E.4594#sh tech-support
***** show version *****
Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to
restrictions as set forth in subparagraph (c) of the Commercial
Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and
subparagraph (c) (1) (11) of the Rights in Technical Data and Computer
Software clause at DFARS sec. 252.227-7013.

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, California 95134-1706
Cisco AP Software, (ap3g3), C2802, RELEASE SOFTWARE
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2020 by Cisco Systems, Inc.
Compiled Wed Jul 29 00:28:31 PDT 2020

ROM: Bootstrap program is U-Boot boot loader
BOOTLDR: U-Boot boot loader Version 2013.01-gacaa15 (Aug 18 2019 - 20:12:19)

AP3C51.0E3E.4594 uptime is 0 days, 0 hours, 2 minutes
Last reload time : Sat Feb 29 23:59:59 UTC 2020
Last reload reason : unknown

cisco AIR-AP2802I-A-K9 ARMv7 Processor rev 1 (v7l) with 1028260/577736K bytes of memory.
Processor board ID FGL2409LH9T
AP Running Image : 8.10.130.0
Primary Boot Image : 8.10.130.0
Backup Boot Image : 0.0.0.0
Primary Boot Image Hash:
Backup Boot Image Hash:
2 Gigabit Ethernet Interfaces
2 802.11 Radios
Radio Driver version : 9.0.5.5-W8964
Radio FW version : 9.1.8.1
HSS FW version : 2.4.28

Base ethernet MAC Address :
Part Number : 0-000000-00
PCA Assembly Number : 800-105672-01
PCA Revision Number : A0
PCR Serial Number : F0C2401627P
```